




Road Safety Recalls Database

Transport Canada Recall # 2010130

Recall Date	2010/04/22
Notification Type	Safety Mfr
System	Lights And Instruments
Manufacturer Recall Number	FL-577
Units Affected 	2,495
Category	Bus, RV Chassis, School Bus, Truck - Med. & H.D.

Recall Details

On certain vehicles, the stop lamps may operate intermittently during light braking applications. Failure of the brake lamps to illuminate when the brakes are applied may result in the following road users being unaware of the driver's intentions, increasing the risk of a crash causing property damage and/or personal injury. Correction: Dealers will replace the hydraulic brake light switch assembly.

Make	Model	Model Year(s) Affected
FREIGHTLINER	BUSINESS CLASS M2	2005 2006 2007 2008 2009 2010 2011
THOMAS BUILT	SAF-T-LINER C2 NON-SCHOOL BUS	2005 2006 2007 2008 2009 2010 2011
THOMAS BUILT	SAF-T-LINER C2 SCHOOL BUS	2005 2006 2007 2008 2009 2010 2011