




Road Safety Recalls Database

Transport Canada Recall # 2011369

Recall Date	2011/10/17
Notification Type	Safety Mfr
System	Electrical
Manufacturer Recall Number	11v-503
Units Affected 	500
Category	School Bus

Recall Details

On certain school buses, the power cable connection (behind the driver's side kick panel) may corrode and cause an electrical fault or short circuit. This could result in a vehicle fire causing property damage and/or personal injury. Correction: Owners will be advised to inspect their vehicle for corrosion in the area of the power terminals and, if excessive corrosion is found, to take the vehicle to an authorized repair facility to have the corrosion removed and the studs and cables replaced.

Make	Model	Model Year(s) Affected
THOMAS BUILT	SAF-T-LINER C2 SCHOOL BUS	2005 2006 2007